ENGINEERING CHANGE NOTICE

Date: 99.12.06			T		ECN #
Date: -74: 12:06					ECN #: 254
Project No.: D206-540			Created By:	Checked	By: OP
Project Name:			Approved By:	Approved	D
206 BASKETS			(proj. manager) A Approved By: (management if req'd) N/4		
Description of Change:					•
raensing DZob-sto	REV.	H 1	O INCORPORATE	DS1 9174	DED 9167
per manuración rec	UES	T.			
THIS DING HAS BEEN APPROVED BY AP OF TO AND IS DONG FUD'D TO PAR					
DSI 9174 / DED 9167 NO LONGER APPLICABLE TO DZ06-540					
DSI 7114 DED 4161 NO CONGER IMPRILABLE TO DZO6-540					
Notification/Acceptance	Affected ✓			Authorization	
QA.	2				
Production	V		MPP002-2001		
Planning N/A		111002 00 1			
Marketing					
Fusing Astions	Yes	No	Responsible	To happen b	y: Complete
Engineering Actions	163	140		49.12.06	99.12.6 DS
Update Blue File Update Pink File	1		DS DS	99.12.06	99.12-06 05
Update D-Part Master Binder		V	<u> </u>	17.1200	79.12-00 03
Update Grey Project Binder			05	99.12.06	99,12.06 DS
Update DEO Binder (Samp "No Lorgar My	<u>. </u>		15	19.12-06	99.12.06 DS
Update Master Document List	,	V		·	
Update Drawing Approval Record	V		DS	99.12.03	99,12.03 DS
IODGALE DIAWING Approval Necond					
Update Change Record form Move Electornic File	1	V	Þ≶	49.12.06	99.12-06 DS
Update Change Record form	1	V	₽2 ₽2		99.12.06 DS 99.12.03 DS
Update Change Record form Move Electornic File		V V	D5 D5	49.12.06	
Update Change Record form Move Electornic File Notify TCA of Change			₽5 ₽5	49.12.06	
Update Change Record form Move Electornic File Notify TCA of Change Notify FAA of Change QST ozl uppme		√ ∨	ÞS	49,12.06 99,12-03	99.(2,03 DS
Update Change Record form Move Electornic File Notify TCA of Change Notify FAA of Change QST ozl uppme		√ ∨	ÞS	49,12.06 99,12-03	99.(2,03 DS
Update Change Record form Move Electornic File Notify TCA of Change Notify FAA of Change QST ozl uppare Notes: WDATE 2d-540-011 013		√ ∨	ÞS	49,12.06 99,12-03	99.(2,03 DS
Update Change Record form Move Electornic File Notify TCA of Change Notify FAA of Change QST ozl uppme		√ ∨	ÞS	49,12.06 99,12-03	99.(2,03 DS
Update Change Record form Move Electornic File Notify TCA of Change Notify FAA of Change QST ozl uppare Notes: WDATE 2d-540-011 013		√ ∨	ÞS	49,12.06 99,12-03	99.(2,03 DS
Update Change Record form Move Electornic File Notify TCA of Change Notify FAA of Change QST ozl uppare Notes: WDATE 2d-540-011 013		√ ∨	ÞS	49,12.06 99,12-03	99.(2,03 DS
Update Change Record form Move Electornic File Notify TCA of Change Notify FAA of Change QST ozl uppare Notes: WDATE 2d-540-011 013		√ ∨	ÞS	49,12.06 99,12-03	99.(2,03 DS
Update Change Record form Move Electornic File Notify TCA of Change Notify FAA of Change QST ozl uppare Notes: WDATE 2d-540-011 013		√ ∨	ÞS	49,12.06 99,12-03	99.(2,03 DS
Update Change Record form Move Electornic File Notify TCA of Change Notify FAA of Change QST ozl uppare Notes: WDATE 2d-540-011 013		√ ∨	ÞS	49,12.06 99,12-03	99.(2,03 DS